



TITLE: DIRECTIONAL MICROPHONE
ASSEMBLY FOR MOUNTING BEHIND A
SURFACE
INVENTOR: Julstrom, Stephen D.
APPLICATION NO.: 09/017937,
CONF. NO. 9038; DOCKET NO. 12078US01
ATTORNEY: Menchaca, PHONE: 312-775-8000

REPLACEMENT SHEET

PRIOR ART




FIG. 1

TITLE: DIRECTIONAL MICROPHONE ASSEMBLY
FOR MOUNTING BEHIND A SURFACE
INVENTOR: Julstrom, Stephen D.
APPLICATION NO.: 09/017937,
CONF. NO. 9038; DOCKET NO. 12078US01
ATTORNEY: Menchaca, PHONE: 312-775-8000

REPLACEMENT SHEET




FIG. 2




FIG. 3

REPLACEMENT SHEET




FIG. 4

REPLACEMENT SHEET

On-Axis Response; +, - 20 Hz Corner Mismatch Responses Compared to Ideal Response




FIG. 5

TITLE: DIRECTIONAL MICROPHONE ASSEMBLY
FOR MOUNTING BEHIND A SURFACE
INVENTOR: Julstrom, Stephen D.
APPLICATION NO.: 09/017937,
CONF. NO. 9038; DOCKET NO. 12078US01
DOCKET NO. 12078US01
ATTORNEY: Menchaca, PHONE: 312-775-8000

REPLACEMENT SHEET

On-Axis Eq'd Response; +, - 20 Hz Corner Mismatch Responses Compared to Ideal Response




FIG. 6

TITLE: DIRECTIONAL MICROPHONE ASSEMBLY
FOR MOUNTING BEHIND A SURFACE
INVENTOR: Julstrom, Stephen D.
APPLICATION NO.: 09/017937,
CONF. NO. 9038; DOCKET NO. 12078US01
ATTORNEY: Menchaca, PHONE: 312-775-8000

REPLACEMENT SHEET




FIG. 7




FIG. 8

TITLE: DIRECTIONAL MICROPHONE ASSEMBLY
FOR MOUNTING BEHIND A SURFACE
INVENTOR: Julstrom, Stephen D.
APPLICATION NO.: 09/017937,
CONF. NO. 9038; DOCKET NO. 12078US01
ATTORNEY: Menchaca, PHONE: 312-775-8000

REPLACEMENT SHEET




FIG. 9




FIG. 10




FIG. 11

TITLE: DIRECTIONAL MICROPHONE ASSEMBLY
FOR MOUNTING BEHIND A SURFACE
INVENTOR: Julstrom, Stephen D.
APPLICATION NO.: 09/017937,
CONF. NO. 9038; DOCKET NO. 12078US01
ATTORNEY: Menchaca, PHONE: 312-775-8000

REPLACEMENT SHEET




FIG. 12

TITLE: DIRECTIONAL MICROPHONE
ASSEMBLY FOR MOUNTING BEHIND A
SURFACE
INVENTOR: Julstrom, Stephen D.
APPLICATION NO.: 09/017937,
CONF. NO. 9038; DOCKET NO. 12078US01
ATTORNEY: Menchaca, PHONE: 312-775-8000

REPLACEMENT SHEET




FIG. 13

REPLACEMENT SHEET




FIG. 14

REPLACEMENT SHEET




FIG. 15